



YR2050 USER MANUAL

Connectors:



Keyboard:




Operations Menu

Press **Menu** button to power On device.

Press and hold **Menu** button to power Off – a menu will appear: **Hold** (Yes) or **▲** (cancel)

1 – Normal Mode (menu item #1)

- Press **Menu**, use **▲▼** to select menu items #1;
- **Menu** (Select) again to activate resistance measurement mode with or without limit reports ;
- Screen divided into the upper left part, with the values of the lower/upper parameters on the left and whether approved (PASS) or not (NO) within the stipulated limits (if acceptance report activated).



Use **Hold** to block new readings.

Use **Range** to select range and auto range modes.

First line:

Left: Range mode: AUTO, 1R, 10R, 100R, 1K – use **Range** to select;

Second line:

Left: **LO**: lower limit , **UP**: lower limit values

Right: result of test – NO or PASS

Example:

It is desired to test a batch of 30 Ω resistors. Those that are within the limits of 29,000 and 30,100 Ω will be accepted.

- Press **Menu**;
- Use **▲▼** for select menu item #5;
- Press **Menu** (again and the screen with the current parameters will be displayed :

5 – ACCEPTANCE REPORT

LO: 1.0000Ω <R

UP: 10.000Ω >RR

Active? Yes(π)/No

- Enter the lower limit value : Use **▲▼** to position in front of LO and **Digit button** to position the digit to be adjusted. . Use **▲▼** again to adjust the desired value.
- Press **Save** button to fix the value;
- Repeat the above steps to set the upper limit;
- Activate report mode:: (Y)

5 – ACCEPTANCE REPORT

LO: 29.9000Ω <R

UP: 30.1000Ω >RR

Active? : Yes(π)/No


- Return to operating mode 1: press **Save** button for return to the main screen.

[AUTO]
LO: 0029.90R
UP: 0030.10R
30.0060Ω
PASS

2 – Cable calculation Mode (menu item #2)

Measure the resistance of a cable, made of a certain material, given two of the following parameters, determine the third: standard resistivity (ρ), area (S) or length (L):

$$R = \rho * L / S$$



First line :

Left: Range mode: AUTO, 1R, 10R, 100R, 1K – use **Range** to select;

Right: actual value of the measured resistance.



The other parameters can only have their values changed if they are not the ones chosen to be calculated.

Fourth line: the parameter to calculate (resistivity **ρ**, length **L** or area **S**);

- Use **▲▼** to go to the 4th line - parameter to calculate
- Use **Hold**(Edit) to edit selected parameter
- Use **▲▼** select parameter to calculate: **ρ** (resistivity), **L** (length), **S** (cable cross-sectional area);



Observe the 2nd and 3rd lines of the display: the data of the parameter being selected becomes “---”, as it will be calculated and not informed;

The unit of measurement appears to the right of the selected parameter;

- For exit from edit parameter press **Hold**(Save) button.



If the component under measurement is accepted, a single beep is emitted when connecting it; if it is rejected, the beep will sound repeatedly.

➔ Measurements above the equipment limits (>4000 ohm) generate overload and are not considered in the report.

Second line:

Left: the resistance value used in the calculations (generally the same as measured by the equipment);

Right: the cable material: custom1, ..., pers8, copper, constantan, silver/manganese, aluminum, iron, gold, silver, platinum, tungsten, nickel-chromium, iron-chromium, nickel-aluminum, pers1 ...

Use ▲ ▼ to go to the parameter (it is completely selected); press **Edit** to change;

Use ▲ ▼ to choose the material; press **Edit** (Save) to exit from edit mode.

Third line:

Left, wire cross-section (area) [mm²];

Right, the length [m];

Use ▲ ▼ to select parameter; press **Edit** to edit parameter; use **Digit** to select the digit to edit (at the point, its position changes);

Use ▲ ▼ change the digit or decimal point position; press **Edit** (Save) to exit from edit mode..

Example 1: a copper cable has a resistivity of 0.00518 Ω. It has a length of 42cm (0.42m). What is your cross section (S)?

➤ Since you want to calculate the cross section, press (▲ ▼) to select the last line.

➤ Press **Hold**(Edit) for parameter selection and (▲ ▼) select **S: ----- mm².**

➤ Press **Hold** (Save) to exit from edit mode.

➤ Enter the length: press (▲ ▼) until the third line is highlighted, **Hold** (Edit); press **Digit** to select the digit to change and (▲ ▼) to adjust; press **Hold** (Save) to exit from edit mode.

➤ Enter the cross-sectional area: repeat the above steps for the area parameter;

➤ Press **Digit button** for cross section (S) will be calculated.

■ [AUTO]	0.00521Ω
R:0.00521Ω	[Copper]
----- mm ²	.4200m
S:1.4080mm ²	

Example 2: A copper cable has a measured resistance 0,00498Ω. . Its cross section (S) is 1,5mm². what is the expected length of this cable?

➤ Press (▲ ▼) until you highlight the last line . Press **Hold** (Edit) and select **l: -----m**

➤ Press **Hold** (Save) to set the parameter to be calculated. .

➤ Input the cross area S press (▲ ▼) until highlighting the third line, area parameter. Press **Hold** (Edit); press Digit pto select the digit to change and (▲ ▼) to adjust.

➤ Press **Hold** (Save) to exit from edit mode.

➤ The cable length will be calculated : l: 42658m

■ [AUTO]	0.00498Ω
R:0.00498Ω	[Copper]
1.500 mm ²	-----m
l:42685m	

Notes: The measured value of the material's electrical resistance is constantly updated, **but the calculated parameter will only be updated when you press Calculate.**

3 – Backlight Setting (menu item #3)

Light: 10 – 99%

Trigger: Always Off (X); Operate; Always On;

Backlight On time: Delay *nn* seconds (5-60sec);

4 – Energy Saving Settings (menu item #4)

Automatic shutdown: Enable (π) /Desable;

Delay time: *nn* min 10-60min, (for automatic shutdown, if active)

Low power mode: Enable (π) /Desable;

Delay: *nn* min, 5-30 min

- Use ▲ ▼ to select parameter

- Use **Digit button** to adjust the parameter value

- Use **Hold** button (Save) to save the parameter value

When entering the low-power mode, display show ----- on resistance value place. For exit from low-power mode press any button.

6 – Serial port (menu item #6)– not used

7 – Calibration (menu item #7) – not used

8 – Restore Calibration (menu item #8) – not used

9 – Contrast Setting (menu item #9)

Contrast: 1-9, default 3

use button **Digit** and **Save** (Hold).

10 – Resistivity Setting (menu item #10)

Used in menu item #5 to determine the length or cross-section of the conductor.

01 – Copper

08 – Platinum

02 – Constantan

09 – Wolframium

03 – Manganin

10 – Nickel chrome

04 – Aluminium

11 – Ferrum-Chromium-Aluminum

05 – Ferrum

12 – Alnico – Nickel-Aluminum

06 – Aurum

13 ... 20 – Personalized

07 – Argentum

Measurement R_{on} of transistors MOS

For transistors N-MOS, cconnect the black clamp to the terminal S, connect the red clamp to the terminal D, add a positive voltage between G and S > Vbr.

For transistors P-MOS, connect the red clamp to the terminal S connect the black clamp to the terminal D. Add a negative voltage between G and S < -Vbr.

Specifications

Display: 120.000 counts

Display update: 4times per second

Voltage protection - max: 20V

Current protection - max: 0,5A

Internal battery : LiIon – 3.7V, 2000mAh, 18650 case

Power consumption:

< 60mA – range 10 Ω and higher, backlight is off ;

<160mA - range 1 Ω , backlight is off

< 10mA in low power mode

Keep batteries charged to at least 50%!

Keyboard

Menu/Select	Hold/ Edit/Save	▲
Range	Calculate/ Digit	▼