



Figure 6.7 Block Diagram of Electrical System

To replace the Logic PCA, see page 7-10.

Wire Harness Assemblies

Check that all connections to the Main Logic Harness Assembly and Power Supply Harness Assembly are solid and that all connectors are attached firmly to the wires. Also ensure that none of the wire insulation is worn or missing.

To replace the Main Logic Harness Assembly, see page 7-14.

To replace the Power Supply Harness Assembly, see page 7-35.