



Remove R1, R2 & C4
Solder R3: 4.7k (or simply put here R2, 10k)
Solder DS18 leg2 somewhere to AIN

Also you can remove C1 & U2 if wanna connect 5V directly to Vcc

