



XT3	
Цепь	Q
L	
N	



XT4	
Цепь	Q
Ud	
AC_18V	
GATE	
0V	
Ilim	
+400V	



XT5	
Q	Цепь
1	0V
2	
3	+400V