


Note:

To put the module in programming mode, perform the steps below with power applied to the module

- 1) Hold down the program button
- 2) Hold down the reset button
- 3) release the reset button
- 4) wait greater than 0.5 seconds
- 5) release the program button

The module should now be in programming mode.



Serial Data To PC

Serial Data From PC

Note, when connecting the serial data connections to an RS232 port on a PC, you must use an RS232 to 3V level shifter IC

Title: Connections Required To Program Module		
Size: A4	Date: 17 feb 2007	Rev: 1v0
KiCad E.D.A.	EESchema (2006-08-28)	Sheet: 1 / 1